



Hardware Information

New customers can purchase hardware from Node1 Internet as part of ordering an internet service. All hardware will be pre-configured for your service. Existing customers can also purchase hardware by contacting us on 08 9964 5464, emailing info@node1.com.au or visiting our store at 218B Lester Avenue, Geraldton WA 6530.

Product Description	Manufacturer	Technical Information	Price	Warranty	Post-Sales Support
Mikrotik QRT-5 AC: High Performance Backbone wireless with 23dBi antenna	Mikrotik	For more information about the Mikrotik QRT visit http://www.mikrotik.com/	\$300	1 year	For support regarding this product please call 08 9964 5464 or visit us in store. If your antenna has become faulty outside of the warranty period a fee of \$300 for a new antenna, and an installation fee of \$55 applies.
Ubiquiti PowerBeam PBE-5AC-300	Ubiquiti	For more information about the Ubiquiti PowerBeam PBE-5AC-300 visit https://www.ubnt.com/airmax/powerbeam-ac/	\$300	1 year	For support regarding this product please call 08 9964 5464 or visit us in store. If your antenna has become faulty outside of the warranty period a fee of \$300 for a new antenna, and an installation fee of \$55 applies.
Ubiquiti PowerBeam PBE-5AC-400	Ubiquiti	For more information about the Ubiquiti PowerBeam PBE-5AC-400 visit https://www.ubnt.com/airmax/powerbeam-ac/	\$300	1 year	For support regarding this product please call 08 9964 5464 or visit us in store. If your antenna has become faulty outside of the warranty period a fee of \$300 for a new antenna, and an installation fee of \$55 applies.
Ubiquiti PowerBeam PBE-5AC-500 with ISO	Ubiquiti	For more information about the Ubiquiti PowerBeam PBE-5AC-500 visit https://www.ubnt.com/airmax/powerbeam-ac/	\$300	1 year	For support regarding this product please call 08 9964 5464 or visit us in store. If your antenna has become faulty outside of the warranty period a fee of \$300 for a new antenna, and an installation fee of \$55 applies.
Ubiquiti PowerBeam PBE-5AC-620 with Radome	Ubiquiti	For more information about the Ubiquiti PowerBeam PBE-5AC-620 visit https://www.ubnt.com/airmax/powerbeam-ac/	\$600	1 year	For support regarding this product please call 08 9964 5464 or visit us in store. If your antenna has become faulty outside of the warranty period a fee of \$600 for a new antenna, and an installation fee of \$55 applies.
NetComm N300 WiFi Gigabit Router with VOIP – NF10WV	NetComm	For more information about the NetComm N300 Wifi Gigabit Router visit http://www.netcommwireless.com/	\$149	1 year	For support regarding this product please call 08 9964 5464 or visit us in store. If the router has been reset and you are unable to bring the router in to our store, or have it reconfigured over the phone, therefore require a technician to attend on site to reconfigure, a fee of \$55 will apply.
NetComm VDSL/ADSL Splitter	NetComm	For more information about the NetComm VDSL/ADSL Splitter visit http://www.netcommwireless.com/	\$20	1 year	For support regarding this product please call 08 9964 5464 or visit us in store.